

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number WA7890008967	2. Page 1 of 1	3. Emergency Response Phone (888) 766-0771	4. Manifest Tracking Number 001553552 JJK	
5. Generator's Name and Mailing Address US DOE IN CARE OF CH2M HILL PLATEAU REMEDIATION CO PO BOX 1600 ATTN: WFMP UHWM RTN MS:T4-04 RICHLAND WA 99352 Generator's Phone: (509)372-1826			Generator's Site Address (if different than mailing address) US DOE IN CARE OF CH2M HILL PLATEAU REMEDIATION CO 2355 STEVENS DRIVE RICHLAND WA 99354			
6. Transporter 1 Company Name MP ENVIRONMENTAL SERVICES			U.S. EPA ID Number CAT00624247			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address CWMW, INC 17629 CEDAR SPRINGS LANE ARLINGTON OR 97812 Facility's Phone: (541)454-2643			U.S. EPA ID Number ORD089452353			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
RQ	1. NA2212, ASBESTOS, 9, PG III, (FRIABLE ASBESTOS)	1	CM	30	Y	X004
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information RETURN TO GENERATOR IF UNABLE TO DELIVER 1. #OR297708; FRIABLE ASBESTOS BUILDING DEBRIS W/ASN-4 FORM ERG 171 (RQ = 1LB) SHIPMENT NUMBER M5028 TOTAL GROSS WEIGHT: 3085 kg ORANGE PANELS NA2212 DISPLAYED TOC JAMES MCGROGAN 509-554-9963 R/c 3800P						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name JAMES MCGROGAN			Signature James P. McGrogan		Month Day Year 09/24/12	
16. International Shipments <input type="checkbox"/> Import to U.S. Transporter signature (for exports only):			<input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:			
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Michael Crause			Signature Michael Crause		Month Day Year 09/24/12	
Transporter 2 Printed/Typed Name			Signature		Month Day Year	
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number:						
18b. Alternate Facility (or Generator) U.S. EPA ID Number						
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H132		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a						
Printed/Typed Name Bob Jo Galvin			Signature Bob Jo Galvin		Month Day Year 09/24/12	

ASN 4

ASBESTOS WASTE SHIPMENT REPORT FORM



PLEASE PRINT OR TYPE! If you have questions, contact your local DEQ Regional Office in Gresham at (503) 667-8414 x 55018, Salem at (503) 378-5086, Medford at (541) 776-6010 ext. 235, or Bend at (541) 388-6146 ext. 226, Pendleton (541) 278-4626, OR call (800) 452-4011 for the location of your local regional DEQ office.

WASTE GENERATOR: (Contractor, Facility, or Operator)

1. Asbestos removal site name and address: U.S. Department of Energy c/o Plateau Remediation Contract
 PO Box 1600 Richland WA Benton 99,352
 Street City/State County Zip
 Contact person: Jeff Westcott Phone: 509-942-8905
2. Operator's name and address: Plateau Remediation Contract Phone: 509-942-8905
 PO Box 1600 MISN Richland WA Benton 99,352
 Street City/State County Zip
3. Waste disposal site: Chemical Waste Management of the North West Phone: 541-454-3220
17629 Cedar Springs Lane Arlington OR Gilliam 97812
 Street City/State County Zip
4. Describe asbestos materials: Wetted doubled bagged, friable asbestos PSN RQ Asbestos 9, NA2212 PGIII
5. Containers: Number: RO/RO box Type: Piping insulation
6. Total quantity (cubic yards): 36-30 sm 9-26-12

7. **OPERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packaged, marked and labeled, and are in all respects in proper condition for transport according to all government regulations. All movement of this asbestos-containing material is recorded on this Waste Shipment Record Form.

Name: Brad Purvis Company: Plateau Remediation Contract
 Signature: *Brad Purvis* Date: 9/24/12

TRANSPORTER(S):

8. Transporter #1: (Acknowledgment of receipt of materials)
 Agent: *Robert Curry* Company: *MRP Environmental*
 Address: *3879 Hwy 30 The Dalles* Phone: *541-980-0476*
 Signature: _____ Date: _____
9. Transporter #2: (Acknowledgment of receipt of materials)
 Agent: _____ Company: _____
 Address: _____ Phone: _____
 Signature: _____ Date: _____

DISPOSAL: (Certification of receipt of asbestos materials covered by this manifest, except as noted in item 11 below.)

10. Waste Disposal Site: *Chemical Waste Management of the Northwest*
 Name and Title: *Dawer* Date: *09-24-12*
 Signature: *Robert Curry* Phone: *541-980-0476*

11. **DISCREPANCY SPACE:** (Add attachments as needed)